



This diagram shows an exploded view of a mechanical assembly. The components are numbered as follows:

- 1:** A bracket or housing at the bottom, indicated by a large bracket.
- 2:** A small bolt or screw.
- 3:** A complex component with a flange and a central port.
- 4:** A cylindrical component with internal features.
- 5:** A small bolt or screw.
- 6:** A circular disc or gasket.
- 7:** A circular disc or gasket.
- 8:** A circular disc or gasket.
- 9:** A cylindrical component with a flange.
- 10:** A small bolt or screw.
- 11:** A small bolt or screw.
- 12:** Two cylindrical components with flanges, shown in pairs.

Dashed lines indicate the assembly path and alignment of the parts.

